

SAINI AUTO SPARES



177, Kohat Enclave, Pitam Pura, Delhi-110034, INDIA. Ph. : 011-28833161 Fax : 011-28877116 Mobile : 09212403662to5,
E-mail : sainiexports@gmail.com, sainiauto@gmail.com,sainibrakes@gmail.com Website:www.brakesofindia.com

S. No.	Product Picture	Product Description	SAINI No.	OE No.	List Price	Type	Bore Dia	Application
1		FRONT LEFT WITH BLEEDER	30041		600	JAPANESE	1.1/4"	EICHER CANTER 10.90 OLD MODEL
		FRONT RIGHT WITH BLEEDER	30042		600			
		RUBBER REPAIR KIT	301041		26			
2		REAR LEFT WITH BLEEDER	30043		700	JAPANESE	1.1/8"	EICHER CANTER 10.90 OLD MODEL
		REAR LEFT WITHOUT BLEEDER	30044		700			
		RUBBER REPAIR KIT	301043		48			
3		REAR RIGHT WITH BLEEDER	30045		700	JAPANESE	1.1/8"	EICHER CANTER 10.90 OLD MODEL
		REAR RIGHT WITHOUT BLEEDER	30046		700			
		RUBBER REPAIR KIT	301043		48			
4		FRONT LEFT WITH BLEEDER	30091		600	TVS	1.1/4"	EICHER CANTER 10.90 LATEST MODEL
		FRONT LEFT WITHOUT BLEEDER	30092		600			
		RUBBER REPAIR KIT	301091		26			
5		FRONT RIGHT WITH BLEEDER	30093		600	TVS	1.1/4"	EICHER CANTER 10.90 LATEST MODEL
		FRONT RIGHT WITHOUT BLEEDER	30094		600			
		RUBBER REPAIR KIT	301091		26			
6		REAR LEFT WITH BLEEDER	30095		700	TVS	1.1/8"	EICHER CANTER 10.90 LATEST MODEL
		REAR LEFT WITHOUT BLEEDER	30096		700			
		RUBBER REPAIR KIT	301095		48			
7		REAR RIGHT WITH BLEEDER	30097		700	TVS	1.1/8"	EICHER CANTER 10.90 LATEST MODEL
		REAR RIGHT WITHOUT BLEEDER	30098		700			
		RUBBER REPAIR KIT	301095		48			
8		FRONT LEFT WITHOUT BLEEDER	30081		600	TVS	1.1/4"	EICHER CANTER 10.90 NEW MODEL
		FRONT LEFT WITH BLEEDER	30082		600			
		RUBBER REPAIR KIT	301042		26			
9		FRONT RIGHT WITHOUT BLEEDER	30083		600	TVS	1.1/4"	EICHER CANTER 10.90 NEW MODEL
		FRONT RIGHT WITH BLEEDER	30084		600			
		RUBBER REPAIR KIT	301042		26			
10		REAR LEFT WITHOUT BLEEDER	30085		700	TVS	1.1/8"	EICHER CANTER 10.90 NEW MODEL
		REAR LEFT WITH BLEEDER	30086		700			
		RUBBER REPAIR KIT	301044		48			
11		REAR RIGHT WITHOUT BLEEDER	30087		700	TVS	1.1/8"	EICHER CANTER 10.90 NEW MODEL
		REAR RIGHT WITH BLEEDER	30088		700			
		RUBBER REPAIR KIT	301044		48			