

SAINI AUTO SPARES



177, Kohat Enclave, Pitam Pura, Delhi-110034, INDIA. Ph. : 011-28833161 Fax : 011-28877116 Mobile : 09212403662to5,
E-mail : sainiexports@gmail.com, sainiauto@gmail.com, sainibrakes@gmail.com Website:www.brakesofindia.com

S. No.	Product Picture	Product Description	SAINI No.	OE No.	List Price	Type	Bore Dia	Application
1		CLUTCH MASTER CYLINDER	16049	29066277	600	TVS	3/4"	TATA 407/608/207/709/ SUMO/SAFARI 10mm THREAD
		REPAIR KIT WITH PISTON & SPRING	501002		160			
		RUBBER REPAIR KIT	501001	29966682	50			
2		CLUTCH MASTER CYLINDER	50009	29066524 29066525	600	TVS	3/4"	TATA 407/608/207/709/ SUMO/SAFARI 12mm THREAD
		REPAIR KIT WITH PISTON & SPRING	501002		160			
		RUBBER REPAIR KIT	501001	29966682	50			
3		CLUTCH MASTER CYLINDER	50011	P7006405	600	KBX	3/4"	TATA 407/608/207/709/ SUMO/SAFARI 10mm THREAD
		REPAIR KIT WITH PISTON & SPRING	106416		160			
		RUBBER REPAIR KIT	106417		50			
4		CLUTCH MASTER CYLINDER	50006	P7011608	600	KBX	3/4"	TATA 407/608/207/709/ SUMO/SAFARI 12mm THREAD
		REPAIR KIT WITH PISTON & SPRING	106416		160			
		RUBBER REPAIR KIT	106417		50			
5		CLUTCH MASTER CYLINDER	50013	29066585	600	TVS	3/4"	TATA 2515/3515 12mm THREAD
		REPAIR KIT WITH PISTON & SPRING	501002		160			
		RUBBER REPAIR KIT	501001	29966682	50			
6		CLUTCH MASTER CYLINDER	50014	29066705	600	TVS	3/4"	TATA 207 12mm THREAD
		REPAIR KIT WITH PISTON & SPRING	501002		160			
		RUBBER REPAIR KIT	501001	29966682	50			
7		CLUTCH MASTER CYLINDER	50045	29066297	800	TVS	15/16"	TATA 1210/2213/1616
		REPAIR KIT WITH PISTON & SPRING	501045	29966708	160			
		RUBBER REPAIR KIT	501046	29966709	60			
8		CLUTCH MASTER CYLINDER	5025-1	29066577	800	TVS	1"	TATA 1210/1312
		REPAIR KIT WITH PISTON & SPRING	5125-1F	29967062	160			
		RUBBER REPAIR KIT	5125-1H	29967063	60			
9		CLUTCH MASTER CYLINDER	5025-2	29066664	800	TVS	1"	TATA LPO1210/1312
		REPAIR KIT WITH PISTON & SPRING	5125-1F	29967062	160			
		RUBBER REPAIR KIT	5125-1H	29967063	60			
10								