

SBRX EXPORTS



177, Kohat Enclave, Pitam Pura, Delhi-110034, INDIA. Ph. : 91-11-28877170 Fax : 91-11-28877116
 Mobile : 09212403662to7, E-mail : sainiexports@gmail.com, Website:www.brakesofindia.com

| S. No. | Product Picture | Product Description | SBRX No. | OE No. | Ref. No. | Price | Bore Dia | Application |
|--------|-----------------|---------------------------------|--------------|-------------|----------|-------|-------------|------------------|
| 1 | | MASTER CYLINDER | MC3125-0006 | | | | 25mm 1" | PATROL |
| | | REPAIR KIT WITH PISTON & SPRING | MK3000-0625 | | | | | |
| | | RUBBER REPAIR KIT | MK3000-0625x | | | | | |
| 2 | | MASTER CYLINDER | MC3138-0007 | | | | 38mm 1.1/2" | 1 TON |
| | | REPAIR KIT WITH PISTON & SPRING | MK3000-0738 | | | | | |
| | | RUBBER REPAIR KIT | MK3000-0738x | | | | | |
| 3 | | MASTER CYLINDER | MC4125-0005 | 46010-T8001 | | | 25mm 1" | CABSTAR |
| | | REPAIR KIT WITH PISTON & SPRING | MK4000-0525 | | | | | |
| | | RUBBER REPAIR KIT | MK4000-0525x | | | | | |
| 4 | | FRONT LEFT WITH BLEEDER | WC5128-0021 | 41102-J5110 | SW-N249 | | 28mm 1.1/8" | CABSTAR |
| | | FRONT LEFT WITHOUT BLEEDER | WC5128-0022 | 41103-J5110 | SW-N250 | | | |
| | | RUBBER REPAIR KIT | WK5000-2128x | | | | | |
| 5 | | FRONT RIGHT WITH BLEEDER | WC5128-0023 | 41100-J5110 | SW-N247 | | 28mm 1.1/8" | CABSTAR |
| | | FRONT RIGHT WITHOUT BLEEDER | WC5128-0024 | 41101-J5110 | SW-N248 | | | |
| | | RUBBER REPAIR KIT | WK5000-2128x | | | | | |
| 6 | | REAR LEFT WITH BLEEDER | WC6123-0002 | | SW-N254 | | 23mm 15/16" | CABSTAR |
| | | REAR LEFT WITHOUT BLEEDER | WC6123-0003 | | SW-N255 | | | |
| | | RUBBER REPAIR KIT | WK6000-0223x | | | | | |
| 7 | | REAR RIGHT WITH BLEEDER | WC6123-0004 | | SW-N252 | | 23mm 15/16" | CABSTAR |
| | | REAR RIGHT WITHOUT BLEEDER | WC6123-0005 | | SW-N253 | | | |
| | | RUBBER REPAIR KIT | WK6000-0223x | | | | | |
| 8 | | FRONT LEFT WITH BLEEDER | | | | | 28mm 1.1/8" | NISSAN |
| | | FRONT LEFT WITHOUT BLEEDER | | | | | | |
| | | RUBBER REPAIR KIT | | | | | | |
| 9 | | FRONT RIGHT WITH BLEEDER | | | | | 28mm 1.1/8" | NISSAN |
| | | FRONT RIGHT WITHOUT BLEEDER | | | | | | |
| | | RUBBER REPAIR KIT | | | | | | |
| 10 | | FRONT LEFT WHEEL CYLINDER | WC5125-0003 | | | | 25mm 1" | PATROL |
| | | FRONT RIGHT WHEEL CYLINDER | WC5125-0004 | | | | | |
| | | RUBBER REPAIR KIT | WK5000-0325x | | | | | |
| 11 | | REAR WHEEL CYLINDER | | | | | | NISSAN |
| | | RUBBER REPAIR KIT | | | | | | |
| | | | | | | | | |
| 12 | | REAR WHEEL CYLINDER | WC6125-0016 | 44100-01J11 | SW-N608 | | 25mm 1" | PATROL NEW MODEL |
| | | RUBBER REPAIR KIT | WK6000-1625x | | | | | |
| | | | | | | | | |